

Table of Contents

1 Requirements and Acceptance for Cable and Wire Harness Assemblies	1-1	2 Applicable Documents	2-1
1.1 Scope	1-1	2.1 IPC	2-1
1.2 Purpose	1-1	2.2 Joint Industry Standards (ANSI J-STD)	2-1
1.3 Approach To This Document	1-1	2.3 Department of Defense (Military)	2-2
1.4 Specialized Designs	1-1	2.4 American National Standards Institute (ANSI)	2-2
1.5 Terms and Definitions	1-1	2.5 ESD Associations (ESDA)	2-2
1.6 Classes of Products	1-1	3 Preparation	3-1
1.7 Document Hierarchy	1-2	3.1 Strand Damage	3-2
1.8 Tool and Equipment Control	1-2	3.2 Conductor - Deformation	3-3
1.9 Observable Criteria	1-2	3.3 Wire Separation (Birdcaging)	3-3
1.10 Defects and Process Indicators	1-3	3.4 Damaged Insulation	3-5
1.11 Inspection Conditions	1-3	4 Soldered Terminations	4-1
1.11.1 Target	1-3	4.1 Wire Preparation, Tinning	4-2
1.11.2 Acceptable	1-3	4.2 Parts Preparation, Gold Removal	4-3
1.11.3 Process Indicator	1-3	4.3 Cleanliness	4-4
1.11.4 Defect	1-3	4.3.1 Prior to Soldering	4-4
1.11.5 Disposition	1-3	4.3.2 Solder Connections	4-4
1.11.6 Product Classification Implied Relationships	1-4	4.3.3 Particulate Matter	4-4
1.11.7 Conditions Not Specified	1-4	4.3.4 Flux Residue	4-5
1.12 Electrical Clearance	1-4	4.4 Insulation	4-6
1.13 Measurement Units and Applications	1-4	4.4.1 Clearance	4-6
1.14 Verification of Dimensions	1-5	4.4.2 Damage from Soldering	4-7
1.15 Visual Inspection	1-5	4.5 Flexible Sleeve Insulation	4-9
1.15.1 Lighting	1-5	4.6 Birdcaged Wire (Soldered)	4-11
1.15.2 Magnification	1-5		
1.16 Electrostatic Discharge (ESD) Protection	1-5		
1.17 Workmanship/Handling	1-5		
1.18 Cleaning	1-5		

Table of Contents (cont.)

4.7 Connection Requirements	4-12	6.2 Discrete Wire Termination	6-9
4.7.1 Terminals	4-12	6.2.1 General	6-9
4.7.2 Turret Terminals	4-12	6.2.2 Position of Wire	6-10
4.7.3 Bifurcated Terminals	4-14	6.2.3 Overhang (Extension)	6-11
4.7.3.1 Side Route Attachments	4-14	6.2.4 Wire Holder	6-13
4.7.3.2 Bottom and Top Route Attachments	4-16	6.2.5 Damage in Connection Area	6-15
4.7.3.3 Staked Wires	4-17	6.2.6 End Connectors	6-16
4.7.4 Slotted Terminals	4-18	6.2.7 Wiremount Connectors	6-18
4.7.5 Pierced/Perforated/Punched Terminals	4-19	6.2.8 Subminiature D-Connector (Series Bus Connector)	6-19
4.7.6 Hook Terminals	4-20	6.2.9 Modular Connectors (RJ Type)	6-21
4.7.7 Cup Terminals	4-21	7 Ultrasonic Welding	7-1
4.7.8 Series Connected Terminals	4-22	7.1 Insulation Clearance	7-2
4.8 Solder Requirements	4-23	7.2 Weld Nugget	7-3
4.8.1 General	4-24	7.2.1 Geometry	7-3
4.8.2 Fillet	4-25	8 Splices	8-1
4.8.3 Turret Terminals	4-27	8.1 Soldered Splices	8-2
4.8.4 Bifurcated Terminals	4-28	8.1.1 Mesh	8-2
4.8.5 Slotted Terminals	4-29	8.1.2 Wrap	8-3
4.8.6 Pierced/Perforated Terminals	4-30	8.1.3 Hook	8-4
4.8.7 Hook Terminals	4-31	8.1.4 Lap	8-5
4.8.8 Cup Terminals	4-32	8.2 Splices - Crimped	8-6
5 Crimp Terminations	5-1	8.2.1 Barrel	8-6
5.1 Stamped and Formed Contacts	5-2	8.2.2 Double Sided	8-8
5.1.1 Insulation Support Crimp	5-3	8.3 Splices - Ultrasonic Welded	8-11
5.1.2 Insulation Inspection Window	5-6	9 Connectorization	9-1
5.1.3 Conductor Crimp	5-7	9.1 Hardware Mounting	9-2
5.1.4 Crimp Bellmouth	5-10	9.1.1 Jackscrews	9-2
5.1.5 Conductor Brush	5-11	9.2 Strain Relief	9-3
5.1.6 Carrier Cutoff Tab	5-14	9.2.1 Sleeving	9-3
5.2 Machined Crimp Contacts	5-15	9.3 Sleeving and Boots	9-4
5.2.1 Insulation Clearance	5-15	9.3.1 Position	9-4
5.2.2 Insulation Support (Insulation Support Style Contacts)	5-17	9.3.2 Bonding - Conductive Adhesive	9-5
5.2.3 Conductor Location	5-18	9.4 Connector Damage	9-7
5.2.4 Crimping	5-20	9.4.1 Criteria	9-7
5.2.5 Under Size Conductor - CMA Buildup Crimps	5-22	9.4.2 Limits - Hard Face - Mating Surface	9-8
6 Insulation Displacement Connection (IDC)	6-1	9.4.3 Limits - Soft Face - Mating Surface or Rear Seal Area	9-9
6.1 Mass Termination, Flat Cable	6-2	9.4.4 Contacts	9-10
6.1.1 End Cutting	6-2		
6.1.2 Notching	6-3		
6.1.3 Planar Ground Plane Removal	6-4		
6.1.4 Connector Position	6-5		
6.1.5 Connector Skew and Lateral Position	6-7		
6.1.6 Retention	6-8		

Table of Contents (cont.)

10 Molding/Potting	10-1	13.2 Center Conductor Termination	13-4
10.1 Molding	10-2	13.2.1 Crimp	13-4
10.1.1 Insulation Damage	10-2	13.2.2 Solder	13-6
10.1.2 Filling	10-3	13.3 Solder Ferrule Pins	13-8
10.1.3 Terminal Positioning	10-5	13.3.1 General	13-8
10.1.4 Fit to Wire or Cable	10-6	13.3.2 Insulation	13-10
10.1.5 Flashing	10-8	13.4 Coaxial Connector - Printed Wire Board Mount	13-11
10.1.6 Chill Marks (Knit Lines), Stress Lines or Cracks	10-9	13.5 Coaxial Connector - Center Conductor Length - Right Angle Connector	13-12
10.1.7 Compound Color	10-9	13.6 Terminal Cover - Soldering	13-14
10.2 Potting	10-10	13.7 Shield Termination	13-16
10.2.1 Filling	10-10	13.7.1 Clamped Ground Rings	13-16
10.2.2 Fit to Wire or Cable	10-11	13.7.2 Crimped Ferrule	13-17
10.2.3 Curing	10-12	13.8 Center Pin Position	13-19
11 Cable Assemblies and Wires	11-1	13.9 Semirigid Coax	13-20
11.1 Cable Assemblies	11-2	13.9.1 Bending and Deformation	13-20
11.1.1 Reference Surfaces	11-2	13.9.2 Surface Condition	13-23
11.1.1.1 Straight/Axial Connectors	11-2	13.9.3 Dielectric Cutoff	13-24
11.1.1.2 Right-Angle Connectors	11-2	13.9.4 Dielectric Cleanliness	13-27
11.1.2 Length Measurement	11-3	13.9.5 Solder	13-28
11.2 Wires (As an Assembly)	11-4	13.10 Swage-Type Connector	13-30
11.2.1 Electrical Terminal Reference Location	11-4	13.11 Soldering and Stripping of Biaxial or Twinaxial Wire - Low Temperature Insulation	13-31
11.2.2 Length Measurement	11-5	13.11.1 Jacket and Tip Installation	13-31
12 Marking/Labeling	12-1	13.11.2 Ring Installation	13-33
12.1 Content	12-2	14 Wire Bundle Securing	14-1
12.2 Legibility	12-2	14.1 Tie Wrap/Lacing Application	14-2
12.3 Permanency	12-4	14.1.1 Tightness	14-6
12.4 Location	12-4	14.1.2 Damage	14-7
12.5 Functionality	12-5	14.1.3 Spacing	14-8
12.6 Marker Sleeve	12-6	14.2 Breakouts	14-9
12.6.1 Wrap Around	12-6	14.2.1 Individual Wires	14-9
12.6.2 Tubular	12-8	14.2.2 Spacing	14-10
13 Coaxial and Twinaxial Cable Assemblies	13-1		
13.1 Stripping	13-2		

Table of Contents (cont.)

<p>14.3 Wire Bundles 14-13</p> <p>14.3.1 Wire Crossover 14-13</p> <p>14.3.2 Coaxial Cable Routing 14-14</p> <p>14.3.3 Unused Wire Termination 14-15</p> <p>14.3.4 Ties over Splices and Ferrules 14-16</p> <p>15 Shielding 15-1</p> <p>15.1 Braided 15-2</p> <p>15.1.1 Direct Applied 15-3</p> <p>15.1.2 Pre-Woven 15-4</p> <p>15.2 Shield Termination 15-5</p> <p>15.2.1 Pick Off 15-5</p> <p>15.2.2 No Pick Off 15-11</p> <p>15.2.3 Low Temperature Insulated Wire - With Pick Off 15-13</p> <p>15.3 Shield Termination - Shrink and Crimp 15-15</p> <p>15.4 Shield Termination - Splicing 15-19</p> <p>15.5 Tapes - Barrier and Conductive, Adhesive or Non-Adhesive 15-21</p> <p>15.6 Conduit (Shielding) 12-22</p> <p>15.7 Conductive Coating 15-23</p> <p>15.8 Shrink Tubing - Conductive Lined 15-24</p> <p>16 Cable/Wire Harness Protective Coverings 16-1</p> <p>16.1 Braid 16-2</p> <p>16.1.1 Direct Applied 16-2</p> <p>16.1.2 Pre-Woven 16-4</p> <p>16.2 Taping 16-5</p> <p>16.3 Sleeving 16-6</p> <p>16.3.1 Shrink Tubing 16-6</p> <p>16.4 Spiral Plastic Wrap (Spiral Wrap Sleeving) 16-7</p> <p>16.5 Conduit (Containment) 16-8</p>	<p>17 Installation 17-1</p> <p>17.1 General 17-2</p> <p>17.2 Hardware Installation 17-3</p> <p>17.2.1 Sequence 17-4</p> <p>17.2.2 Type and Missing 17-6</p> <p>17.2.3 Minimum Torque for Electrical Connections 17-7</p> <p>17.2.4 Wires 17-8</p> <p>17.2.5 High Voltage Applications 17-11</p> <p>17.3 Wire/Harness Installation 17-12</p> <p>17.3.1 Stress Relief 17-12</p> <p>17.3.2 Wire Dress 17-13</p> <p>17.3.3 Service Loops 17-14</p> <p>18 Solderless Wrap 18-1</p> <p>18.1 Number of Turns 18-2</p> <p>18.2 Turn Spacing 18-3</p> <p>18.3 End Tails, Insulation Wrap 18-4</p> <p>18.4 Raised Turns Overlap 18-6</p> <p>18.5 Connection Position 18-7</p> <p>18.6 Wire Dress 18-9</p> <p>18.7 Wire Slack 18-10</p> <p>18.8 Plating 18-11</p> <p>18.9 Damage 18-12</p> <p>18.9.1 Insulation 18-12</p> <p>18.9.2 Wires and Terminals 18-13</p> <p>Appendix A A-1</p> <p>Appendix B B-1</p> <p>Standard Improvement Form</p>
--	--